

Under Review Notification

Raised By: Ketan Tailor
Date: 12/05/2019

Product #: RBW0905G12351-3G
Product Name: Pivot Shear Bolt

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank								Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
RBW0905G12351-3G	RBW0905G12351-3G REV. C	Y	Y	N	Y	Y	Y	N	N	19-1304	Drawing Update

Description of Issue:

Items -14 and -17 in RBW0905G12631-3G (Safety Pin, Towing/Pushing) specify a minimum installed inner diameter of 0.3933 [9.99] and 0.3145 [7.99]. Due to tolerance stack up, it is possible that the Pivot Shear Bolt cannot be installed on the Safety Pin, Towing/Pushing. The drawing must be updated to modify 0.391+0.000/-0.002 and 0.312+0.000/-0.002 diameters and add GD&T as required.

Distribution:	VP Operations	Director of Engineering	Customer Support Manager	Technical Support
	Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
	Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
	QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene